OT Roll Offs 2/11/2015

Number	Original Profile	Status		Analyzed	Approved
OT 25563	Not Applicable	Sand Trench Residue			Current
OT 25337	Not Applicable	Empty			
OT 25474	Not Applicable	Empty			
OT 25480	Not Applicable	Fine material, soil sand from North Pond Asphalt	6	No	
OT 25160	Not Applicable	Sand from Warehouse	6	No	
OT 25452	Not Applicable	Sand from Warehouse	6	No	
OT 25319	Not Applicable	Debris (ADS Hose, Wood, Pails, Plastic, PPE)	7	No	
OT 25134	Not Applicable	Debris (Pails, PPE, Wood)	7	No	

Vacuum BoxesReady to ShipDonated2/11/2015

Number	Original Profile	Status	Composite	Analyzed	Approved
VB 2564		Sludge from WWT Area	Sludge Comp 3	Received Results	24"
VB 25318		Sludge S T 2	Sludge Comp 5	Received Results	37 "
VB 25306		Sludge S T 2, S T 5	Sludge Comp 5	Received Results	36.5"
VB 25302		Sludge N T 3, N T 5, N T 6, S T 8 N OT 8	Sludge Comp 3 *****	Received Results	36"
VB 2501		Sludge N T 3, N T 5, N T 6, S T 8	Sludge Comp 3	Received Results	36"
VB 25278		Sludge N T 9, N T 10, N T 11	Sludge Comp 5	Received Results	36.5"
VB 25226		Sludge S T 3, S T 5, S T 7	Sludge Comp 2	Received Results	36"
VB 25348		Sludge S T 5	Sludge Comp 3	Received Results	36"
VB A 0825097		Sludge ST 5	Sludge Comp 3	Received Results	36"
VB A 785		Sludge ST 5			36"
VB 25206		Sludge ST 5			36"
VB 25274		Sludge ST 5			36"
VB 25341		Sludge ST 8			36"
VB 25251		Sludge ST 8			36"
VB 25322		Sludge ST 8			36"
VB 25287		Sludge N OT 7			36"
VB 25333		Sludge N OT 8			36"
VB 25146		Empty			
VB 25281		Sludge N OT 8			36"
VB 25343		SludgeN OT 8			14"
VB 25203		Empty			
VB 25315		Empty			

Dewatering Box

Number	Status	Analyzed	Approved
VBDW 25196	N OT 8	No	28"

Frac Tanks

Number	Status	Analyzed	Approved
FT 1004	Full Approved Lonestar Qualifying w/CB&I	Yes	
FT 1002	Empty-Cleaned	NA	
FT 1001	Full Approved Lonestar Profile LSE 1128 Out 2/16/2015	Yes	Profile LSE 1128
FT 5180	Empty-Some residual sludge	NA	
FT 215012	Full-Analysis Pending	Preliminary	
FT 30335	5,060 Gallons		
FT 33527	Empty-Cleaned	NA	
FT 30338	Empty-Cleaned	NA	